REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/10/2016	**Time:**	9:13 AM
Name of School Corporation:	SHERIDAN COMMUNITY SCHOOLS			**Corp ID:**	293055
Address of School Corporation:	24795 Hinsley Rd				
City:	Sheridan	**Zip:**	46069	**County Number:**	29
VIN:	4DRBUSKN0EB403453	**License Number:**	7615	**Bus Number:**	7
Make of Body:	IC Corporation **Year:** 2014	**Make of Chassis:**	IC Corporation	**Year:**	2014
Bus Type:	C	**Mileage:**	35480		
Inspection Status:	R	**Inspected By:**	Edwin Davis	**PE:**	3981

Violations - Rejected

Inspection Code	Description
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
70-1-5	There are any decals or stickers, except those required by law, in the windshield or in the windows to the immediate right or left of the driver

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.