

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/21/2016	Time:	9:09 AM
Name of School Corporation:	SOUTHWEST PARKE COMM SCH CORP	Corp ID:	616260		
Address of School Corporation:	RR 1				
City:	Montezuma	Zip:	47862	County Number:	61
VIN:	4DRBUAAN7CB454683	License Number:	B637C	Bus Number:	12
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	44698	Year:	2012
Inspection Status:	R	Inspected By:	Tyler VanNess	PE:	7583

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
68-1-1	Washers do not function properly in any manner
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.