REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 6/21/2016 Time: 9:09 AM 616260

Name of School Corporation: SOUTHWEST PARKE COMM SCH CORP Corp ID:

Address of School Corporation: RR 1

City: Montezuma Zip: 47862 **County Number: 61** VIN: 4DRBUAAN7CB454683 **Bus Number:** License Number: B637C 12 Make of Body: 2012 IC Corporation Year: 2012 Make of Chassis: IC Corporation Year:

Bus Type: С Mileage: 44698

PE: 7583 **Inspection Status:** R Inspected By: Tyler VanNess

Violations - Rejected

Inspection Code Description

68-1-1 Washers do not function properly in any manner

82-1-2 The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.