

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 6/23/2016 **Time:** 10:47 AM
Name of School Corporation: RICHLAND-BEAN BLOSSOM C.S.CORP **Corp ID:** 535705
Address of School Corporation: 600 S Edgewood Dr
City: Ellettsville **Zip:** 47429 **County Number:** 53
VIN: 4DRBUAFN75B979917 **License Number:** 20509 **Bus Number:** 40
Make of Body: IC Corporation **Year:** 2005 **Make of Chassis:** IC Corporation **Year:** 2005
Bus Type: C **Mileage:** 192812
Inspection Status: A **Inspected By:** Mark Raper **PE:** 6473

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.