

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 6/29/2016 Time: 8:37 AM
Name of School Corporation: HONEY GROVE EDUCATIONAL DAYCARE Corp ID: 41001Z
Address of School Corporation: 1709 S SR 135
City: Greenwood Zip: 46143 County Number: 41
VIN: 1GBHG31RXX1146766 License Number: B958AB Bus Number: 2
Make of Body: Chevrolet Year: 1999 Make of Chassis: Chevrolet Year: 1999
Bus Type: Mileage: 121214
Inspection Status: O Inspected By: John Pang PE: 6196

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (1/2) inch in diameter.

Bus Type Description