## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual **Date:** 6/29/2016 **Time:** 8:37 AM **Name of School Corporation:** HONEY GROVE EDUCATIONAL DAYCARE **Corp ID:** 41001Z

Address of School Corporation: 1709 S SR 135

City:GreenwoodZip:46143County Number:41VIN:1GBHG31RXX1146766License Number:B958ABBus Number:2Make of Body:Chevrolet Year:1999Make of Chassis:Chevrolet Year:1999

Bus Type: Mileage: 121214

Inspection Status: O Inspected By: John Pang PE: 6196

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

44-1-1 Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

**Violations - Out of Service** 

Exhaust leak exceeding one (1) inch measurable in any direction or half (½) inch in diameter.

**Bus Type Description**