REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/29/2016	**Time:**	8:37 AM
Name of School Corporation:	HONEY GROVE EDUCATIONAL DAYCARE			**Corp ID:**	41001Z
Address of School Corporation:	1709 S SR 135				
City:	Greenwood	**Zip:**	46143	**County Number:**	41
VIN:	1GBHG31RXX1146766	**License Number:**	B958AB	**Bus Number:**	2
Make of Body:	Chevrolet **Year:** 1999	**Make of Chassis:**	Chevrolet	**Year:**	1999
Bus Type:		**Mileage:**	121214		
Inspection Status:	O	**Inspected By:**	John Pang	**PE:**	6196

Violations - Rejected

Inspection Code	Description
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code	Description
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (Â½) inch in diameter.

Bus Type Description