

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 7/7/2016	<b>Time:</b> 9:14 AM
<b>Name of School Corporation:</b> M.S.D. STEUBEN COUNTY	<b>Corp ID:</b> 767615	
<b>Address of School Corporation:</b> 400 S Martha St		
<b>City:</b> Angola	<b>Zip:</b> 46703	<b>County Number:</b> 76
<b>VIN:</b> 4UZABRCS87CX41176	<b>License Number:</b> 15963	<b>Bus Number:</b> 111
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2007	<b>Make of Chassis:</b> Freightliner
<b>Year:</b> 2007	<b>Mileage:</b> 156274	<b>Year:</b> 2007
<b>Bus Type:</b> C		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Eric Egbert	<b>PE:</b> 7006

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-7	If bus manufactured after 5-2-1994, one (1) inch reflective tape is not applied to the door outline, is missing, or badly faded (two (2) is permissible on bumper below door if insufficient space on body

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**