

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 7/12/2016	Time: 7:10 AM	
Name of School Corporation: AVON COMMUNITY SCHOOLS	Corp ID: 323315		
Address of School Corporation: 7203 E HWY 36			
City: Avon	Zip: 46123	County Number: 32	
VIN: 4DRBWAAR59A070767	License Number: 31473	Bus Number: 56	
Make of Body: IC Corporation	Year: 2009	Make of Chassis: IC Corporation	Year: 2009
Bus Type: D	Mileage: 78198		
Inspection Status: A	Inspected By: John Pang	PE: 6196	

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.