## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	7/12/2016	Time:	7:57 AM
Name of School Co	orporation: AVON	<b>COMMUNITY</b>	SCHOOLS		Corp ID:	323315
Address of School	Corporation:	7203 E HWY 3	6			
City:	Avon	Zip:	46123		<b>County Number:</b>	32
VIN:	4DRBWAAR19A0707	765	License Number:	31978	Bus Number:	21
Make of Body:	IC Corporation Year:	2009	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	D		Mileage:	65684		
Inspection Status:	А	Inspected By:	John Pang		PE:	6196

**Violations - Rejected** 

Inspection Code Description

Violations - Out of Service

Inspection Code Description

## Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.