## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:7/12/2016Time:9:40 AMName of School Corporation:AVON COMMUNITY SCHOOLSCorp ID:323315

Address of School Corporation: 7203 E HWY 36

City:AvonZip:46123County Number:32VIN:4DRBUSKN7BB327340License Number:74315Bus Number:66Make of Body:IC Corporation Year:2011Make of Chassis:IC Corporation Year:2011

Bus Type: C Mileage: 55346

Inspection Status: A Inspected By: John Pang PE: 6196

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.