

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 7/21/2016	Time: 9:16 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP.	Corp ID: 80750	
Address of School Corporation: 2 S 3rd St.		
City: Flora	Zip: 46929	County Number: 8
VIN: 4DRBUSKN8EB765918	License Number: 6222	Bus Number: 18
Make of Body: IC Corporation	Year: 2014	Make of Chassis: IC Corporation
Year: 2014	Mileage: 44476	Year: 2014
Bus Type: D		
Inspection Status: O	Inspected By: Nate King	PE: 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
17-1-1	Any dome light is inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-4	Stop arm does not function properly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.