REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 7/21/2016 **Time:** 1:02 PM

Name of School Corporation: CARROLL CONS. SCHOOL CORP. Corp ID: 80750

Address of School Corporation: 2 S 3rd St.

City:FloraZip:46929County Number:8VIN:1FDWE35F13HB85204License Number:66833Bus Number:2sbMake of Body:Mid Bus, Inc. Year:2003Make of Chassis:FordYear:2003

Bus Type: Mileage: 97873

Inspection Status: A Inspected By: Nate King PE: 7421

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description