# REPORT OF SCHOOL BUS INSPECTION

9:14 Type of Annual Date: 8/5/2016 **Time**: Inspection: AM Name of School Corporation: **LUTHERAN HIGH SCHOOL** 49C270 Corp ID: **Address of School Corporation:** 5555 S Arlington Ave County City: Indianapolis Zip: 46237 49 Number: License VIN: 1GBHG31R1Y1116895 954FC **Bus Number:** 2 Number: Make of Thomas Built Buses, Chevrolet Year: Year: 2001 Make of Body: 2001 Inc. Chassis: **Bus Type:** A1 Mileage: 18799 Inspected PE: **Inspection Status:** O **Edwin Davis** 3981 By:

## Violations - Rejected

### Inspection Code

### **Description**

12-1-1 Clearance light is missing, cracked, faded, wrong color, or inoperative.

### **Violations - Out of Service**

Inspection Code Description

19-2-4 Door glass is cracked.

# **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.