

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/11/2016	Time:	9:38 AM
Name of School Corporation:	BARTHOLOMEW CONS. SCHOOL CORP.	Corp ID:	30365		
Address of School Corporation:	1260 N Marr Rd				
City:	Columbus	Zip:	47201	County Number:	3
VIN:	1BAANCPA63F212161	License Number:	19228	Bus Number:	230
Make of Body:	Blue Bird Corporation	Year:	2003	Make of Chassis:	Blue Bird Corporation
Bus Type:	D	Mileage:	148817		
Inspection Status:	O	Inspected By:	Travis Coryea	PE:	5892

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code

Description

24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
--------	---

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.