

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/15/2016	Time:	7:27 AM		
Name of School Corporation:	AVON COMMUNITY SCHOOLS			Corp ID:	323315		
Address of School Corporation:	7203 E HWY 36						
City:	Avon	Zip:	46123	County Number:	32		
VIN:	1BAKJCBA2HF328102		License Number:	12508	Bus Number:	78	
Make of Body:	Blue Bird Corporation	Year:	2017	Make of Chassis:	Blue Bird Corporation	Year:	2017
Bus Type:	C			Mileage:	1696		
Inspection Status:	O	Inspected By:	Edwin Davis	PE:	3981		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
23-1-6	Tailpipe does not extend to, or extends beyond the perimeter of the bus body

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.