REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	8/19/2016	**Time:**	9:35 AM
Name of School Corporation:	MARQUETTE HIGH SCHOOL			**Corp ID:**	71002Z
Address of School Corporation:	306 W 10th St.				
City:	Michigan City **Zip:**	46306		**County Number:**	46
VIN:	1GBHG31R6Y1201361	**License Number:**	b872aa	**Bus Number:**	1
Make of Body:	Chevrolet **Year:** 2000	**Make of Chassis:**	Corbeil	**Year:**	2000
Bus Type:		**Mileage:**	108946		
Inspection Status:	O **Inspected By:**	Dale Morgan		**PE:**	4743

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
50-2-1	There is no seat belt cutter in the vehicle

Bus Type Description