

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |                |                         |                |
|---------------------------------------|--------------------------------|------------------------|----------------|-------------------------|----------------|
| <b>Type of Inspection:</b>            | Out of Service                 | <b>Date:</b>           | 8/22/2016      | <b>Time:</b>            | 4:25 PM        |
| <b>Name of School Corporation:</b>    | EVANSVILLE-VANDERBURGH SCH COR | <b>Corp ID:</b>        | 827995         |                         |                |
| <b>Address of School Corporation:</b> | 951 Walnut St                  |                        |                |                         |                |
| <b>City:</b>                          | Evansville                     | <b>Zip:</b>            | 47713          | <b>County Number:</b>   | 82             |
| <b>VIN:</b>                           | 1HVBBABP94H579896              | <b>License Number:</b> | B755B          | <b>Bus Number:</b>      | N86            |
| <b>Make of Body:</b>                  | Blue Bird Corporation          | <b>Year:</b>           | 2004           | <b>Make of Chassis:</b> | IC Corporation |
| <b>Bus Type:</b>                      | C                              | <b>Mileage:</b>        | Unknown        |                         |                |
| <b>Inspection Status:</b>             | O                              | <b>Inspected By:</b>   | Bradley Miller | <b>PE:</b>              | 7809           |

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 8-2-11                 | There is any defect not in compliance with the minimum school bus brake inspection standards |

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**