

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/24/2016	Time:	1:49 PM		
Name of School Corporation:	LAWRENCEBURG COMM. SCHOOL CORP			Corp ID:	151620		
Address of School Corporation:	300 Tigar Blvd						
City:	Lawrenceburg	Zip:	47025	County Number:	15		
VIN:	1BABNCPA1CF285345		License Number:	966	Bus Number:	6	
Make of Body:	Blue Bird Corporation	Year:	2012	Make of Chassis:	Blue Bird Corporation	Year:	2012
Bus Type:	D			Mileage:	55548		
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665		

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.