

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Semi-Annual      **Date:** 9/19/2016      **Time:** 9:35 AM  
**Name of School Corporation:** ELWOOD COMMUNITY SCHOOL CORP.      **Corp ID:** 485280  
**Address of School Corporation:** 1306 N Anderson St  
**City:** Elwood      **Zip:** 46036      **County Number:** 48  
**VIN:** 1GDHG31F3X1065346      **License Number:** 25960      **Bus Number:** A1  
**Make of Body:** Corbeil      **Year:** 1999      **Make of Chassis:** GMC      **Year:** 1999  
**Bus Type:**      **Mileage:** 51682  
**Inspection Status:** A      **Inspected By:** Jeremy Mason      **PE:** 8139

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

Bus Type Description