

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                             |                        |            |                         |                          |
|---------------------------------------|-----------------------------|------------------------|------------|-------------------------|--------------------------|
| <b>Type of Inspection:</b>            | Registration                | <b>Date:</b>           | 9/23/2016  | <b>Time:</b>            | 7:52 PM                  |
| <b>Name of School Corporation:</b>    | M.S.D. MARTINSVILLE SCHOOLS | <b>Corp ID:</b>        | 555925     |                         |                          |
| <b>Address of School Corporation:</b> | PO Box 1416                 |                        |            |                         |                          |
| <b>City:</b>                          | Martinsville                | <b>Zip:</b>            | 46151      | <b>County Number:</b>   | 55                       |
| <b>VIN:</b>                           | 4UZABRBT49CAE8288           | <b>License Number:</b> | B331E      | <b>Bus Number:</b>      | 3                        |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.    | <b>Year:</b>           | 2009       | <b>Make of Chassis:</b> | Thomas Built Buses, Inc. |
| <b>Bus Type:</b>                      | C                           | <b>Mileage:</b>        | Unknown    | <b>Year:</b>            | 2209                     |
| <b>Inspection Status:</b>             | A                           | <b>Inspected By:</b>   | Mark Raper | <b>PE:</b>              | 6473                     |

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**