

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	9/26/2016	Time:	9:34 AM
Name of School Corporation:	SOUTH DEARBORN COMM. SCH. CORP			Corp ID:	151600
Address of School Corporation:	6109 Squire Place				
City:	Aurora	Zip:	47001	County Number:	15
VIN:	1GDL7T1J1TJ501524	License Number:	unde	Bus Number:	23A
Make of Body:	GMC	Year:	1996	Make of Chassis:	GMC
Bus Type:	B	Mileage:	130580	Year:	1996
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
22-2-2	There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.