

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 10/3/2016 **Time:** 9:44 AM
Name of School Corporation: BATESVILLE COMM. SCHOOL CORP. **Corp ID:** 696895
Address of School Corporation: 626 N Huntersville Rd
City: Batesville **Zip:** 47006 **County Number:** 69
VIN: 4UZAAXBW23CL71610 **License Number:** B688F **Bus Number:** 60
Make of Body: Freightliner **Year:** 2003 **Make of Chassis:** Freightliner **Year:** 2003
Bus Type: C **Mileage:** 137594
Inspection Status: O **Inspected By:** Chris Clark **PE:** 6665

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code

Description

24-2-1 There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.