REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspec	tion	Date:	10/5/2016	Time:	8:22 PM
Name of School Corporation:RICHAddress of School Corporation:			EAN BLOSSOM C.S	Corp ID:	535705	
Address of Scho	or corporation:	600 S E	dgewood Dr		County	
City:	Ellettsville	Zip:	47429		Number:	53
VIN:	1BAKJCPAXFF311909		License Number:	NBRBB35	Bus Number:	35
Make of Body:	Blue Bird Corporation	Year: 2015	Make of Chassis:	Blue Bird Corporation	Year:	2015
Bus Type:	С		Mileage:	2601		
Inspection Status:	0	Inspecte By:	ed Mark Raper		PE:	6473

Violations - Rejected

Inspection CodeDescription11-1-2The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.