

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	10/6/2016	Time:	9:27 AM		
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			Corp ID:	131300		
Address of School Corporation:	5808 E Administration Rd						
City:	Marengo	Zip:	47140	County Number:	13		
VIN:	1HVBABPXWH624766		License Number:	B867A	Bus Number:	24	
Make of Body:	Blue Bird Corporation	Year:	1999	Make of Chassis:	Blue Bird Corporation	Year:	1999
Bus Type:	C			Mileage:	215807		
Inspection Status:	O	Inspected By:	Travis Coryea	PE:	5892		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
57-1-2	Step-well area is weakened
2-1-1	Required back-up lights do not function.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
57-2-1	Any part of the step-well or support structure is rusted through
8-2-5	There is brake fluid leaking at any point

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.