REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:10/6/2016Time:9:33 AMName of School Corporation:CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:1HVBBABP5XH208769License Number:Bus Number:26Make of Body:IC Corporation Year:1999Make of Chassis:IC Corporation Year:1999

Bus Type: C Mileage: 126795

Inspection Status: A Inspected By: Travis Coryea PE: 5892

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.