

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 10/6/2016 **Time:** 10:00 AM
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP **Corp ID:** 131300
Address of School Corporation: 5808 E Administration Rd
City: Marengo **Zip:** 47140 **County Number:** 13
VIN: 1HVBBAAP0XH232236 **License Number:** B331G **Bus Number:** 33
Make of Body: IC Corporation **Year:** 1999 **Make of Chassis:** IC Corporation **Year:** 1999
Bus Type: C **Mileage:** 137461
Inspection Status: R **Inspected By:** Travis Coryea **PE:** 5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-2	Excessive effort is needed to open the emergency door
29-1-1	The flooring is improper
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.