## REPORT OF SCHOOL BUS INSPECTION

Type of Semi-Annual 10/6/2016 **Time**: 7:40 PM Date: Inspection: CRAWFORD CO. COMM. SCHOOL CORP Name of School Corporation: 131300 Corp ID: **Address of School Corporation:** 5808 E Administration Rd County City: Marengo Zip: 47140 13 Number: License VIN: B951B 22 1GBL7T1C01J509024 **Bus Number:** Number: Blue Bird Make of Year: 2002 Chevrolet Year: Make of Body: 2002 Corporation Chassis: **Bus Type:** С Mileage: 187988 Inspected PE: 5892 **Inspection Status:** R Travis Coryea By:

## Violations - Rejected

<u>Inspection</u> <u>Code</u>	<u>Description</u>
46-1-2	Any seat back or bottom is loose
63-1-3	Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.