REPORT OF SCHOOL BUS INSPECTION

Type of 9:33 Semi-Annual 10/13/2016 **Time**: Date: Inspection: AM CRAWFORD CO. COMM. SCHOOL CORP Name of School Corporation: 131300 Corp ID: **Address of School Corporation:** 5808 E Administration Rd County City: Marengo Zip: 47140 13 Number: License VIN: 1GDL7T1C8XJ515850 B931B **Bus Number:** 17 Number: Make of Blue Bird Year: 2000 GMC Make of Body: Year: 2000 Corporation Chassis: **Bus Type:** С Mileage: 132052 Inspected PE: **Inspection Status:** R Travis Coryea 5892 By:

Violations - Rejected

Inspection Code

Description

29-1-2

Floor covering is missing, cut, loose, buckled, bulging, or not secure

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.