

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 10/19/2016 **Time:** 10:35 AM
Name of School Corporation: HANOVER COMM. SCHOOL CORP. **Corp ID:** 454580
Address of School Corporation: PO Box 645
City: Cedar Lake **Zip:** 46303 **County Number:** 45
VIN: 4DRBUAANXFB657197 **License Number:** 9726 **Bus Number:** 19
Make of Body: IC Corporation **Year:** 2015 **Make of Chassis:** IC Corporation **Year:** 2015
Bus Type: C **Mileage:** 24590
Inspection Status: A **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.