

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	10/24/2016	<b>Time:</b>	9:03 AM
<b>Name of School Corporation:</b>	MONROE COUNTY COMM. SCH. CORP.			<b>Corp ID:</b>	535740
<b>Address of School Corporation:</b>	505 E North Dr				
<b>City:</b>	Bloomington	<b>Zip:</b>	47401	<b>County Number:</b>	53
<b>VIN:</b>	1T7YT3C2351156059	<b>License Number:</b>	20527	<b>Bus Number:</b>	50
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2005	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	D	<b>Mileage:</b>	119507	<b>Year:</b>	2005
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Mark Raper	<b>PE:</b>	6473

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-2	There are intersecting cracks in the windshield area covered by the wipers
70-1-4	There is any cracked glass to the immediate right or left of the driver

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type D School Bus** – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.