## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	n		Date:	10/24/2016	Time:	9:03 AM
Name of School Address of School	Corporation: ool Corporation:	MONI	ROE COUNT 505 E North	Y COMM. SCH. Dr	CORP.	Corp ID:	535740
City:	Bloomington		Zip:	47401		County Number:	53
VIN:	1T7YT3C2351156059	-		License Number:	20527	Bus Number:	50
Make of Body:	Thomas Built Buses, Inc.	Year:	2005	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2005
Bus Type:	D			Mileage:	119507		
Inspection Status:	0		Inspected By:	Mark Raper		PE:	6473

## Violations - Rejected

## <u>Inspection Code</u> <u>Description</u>

70-1-2 There are intersecting cracks in the windshield area covered by the wipers 70-1-4 There is any cracked glass to the immediate right or left of the driver

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.