

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	10/27/2016	<b>Time:</b>	9:23 AM
<b>Name of School Corporation:</b>	KNOX COMMUNITY SCHOOL CORP.			<b>Corp ID:</b>	757525
<b>Address of School Corporation:</b>	2 Redskin Trail				
<b>City:</b>	Knox	<b>Zip:</b>	46534	<b>County Number:</b>	75
<b>VIN:</b>	1T88R3B1511101562	<b>License Number:</b>	880	<b>Bus Number:</b>	48
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2001	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	D	<b>Mileage:</b>	142066	<b>Year:</b>	2001
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Nathan Sherer	<b>PE:</b>	7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-1	Required back-up lights do not function.
16-1-1	There are any leaks from the differential, pinion seal, or either rear wheel seal
37-1-1	The horn does not operate at all

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
65-2-1	Warning lights fail to operate correctly

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**