

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	11/2/2016	Time:	9:15 AM
Name of School Corporation:	SEYMOUR COMMUNITY SCHOOLS	Corp ID:	363675		
Address of School Corporation:	1638 S Walnut St				
City:	Seymour	Zip:	47274	County Number:	36
VIN:	1T7Y84D29H1113081	License Number:	12946	Bus Number:	40
Make of Body:	Thomas Built Buses, Inc.	Year:	2017	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D	Mileage:	7200		
Inspection Status:	O	Inspected By:	Travis Coryea	PE:	5892

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code

Description

24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
--------	---

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.