## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:11/3/2016 Time:9:32 AMName of School Corporation:MARQUETTE HIGH SCHOOLCorp ID:71002Z

Address of School Corporation: 306 W 10th St.

City:Michigan CityZip:46306County Number: 46VIN:1GBHG31R6Y1201361License Number: b872aaBus Number: 1Make of Body:Chevrolet Year: 2000Make of Chassis: CorbeilYear: 2000

Bus Type: Mileage: 109920

Inspection Status: R Inspected By: Nathan Sherer PE: 7029

**Violations - Rejected** 

<u>Inspection Code</u> <u>Description</u>

17-1-1 Any dome light is inoperative

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**