

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 11/16/2016	Time: 1:05 PM
Name of School Corporation: RICHLAND-BEAN BLOSSOM C.S.CORP	Corp ID: 535705	
Address of School Corporation: 600 S Edgewood Dr		
City: Ellettsville	Zip: 47429	County Number: 53
VIN: 4DRBRAAN74B967239	License Number: 19776	Bus Number: 19
Make of Body: IC Corporation	Year: 2004	Make of Chassis: IC Corporation
Year: 2004	Mileage: 91412	Year: 2004
Bus Type: C		
Inspection Status: O	Inspected By: Mark Raper	PE: 6473

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.