

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	11/29/2016	<b>Time:</b>	10:36 AM
<b>Name of School Corporation:</b>	ANDERSON COMM. SCHOOL CORP.			<b>Corp ID:</b>	485275
<b>Address of School Corporation:</b>	1600 Hillcrest Ave				
<b>City:</b>	Anderson	<b>Zip:</b>	46011	<b>County Number:</b>	48
<b>VIN:</b>	4UZAAXCS14CM20907	<b>License Number:</b>	B944B	<b>Bus Number:</b>	23
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2004	<b>Make of Chassis:</b>	Freightliner
<b>Year:</b>	2003	<b>Mileage:</b>	132728	<b>PE:</b>	8139
<b>Bus Type:</b>	C	<b>Inspected By:</b>	Jeremy Mason		
<b>Inspection Status:</b>	O				

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-2	The seat belt cutter is not secured
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
29-1-5	Prohibited area sign is missing or obscured

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**