

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	12/16/2016	Time:	1:31 PM
Name of School Corporation:	NETTLE CREEK SCHOOL CORP.			Corp ID:	898305
Address of School Corporation:	795 Baker Rd				
City:	Hagerstown	Zip:	47346	County Number:	89
VIN:	1T88T4C2571281939	License Number:	3461	Bus Number:	14
Make of Body:	Thomas Built Buses, Inc.	Year:	2007	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D			Mileage:	144477
Inspection Status:	O	Inspected By:	Jeremy Mason	PE:	8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
64-1-4	Any front turn signal does not function properly
17-1-1	Any dome light is inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-2	Stop arm lights do not flash
59-2-4	Stop arm does not function properly
59-2-1	Any stop arm light is inoperative
65-2-1	Warning lights fail to operate correctly

### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.