

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 12/22/2016 **Time:** 6:36 AM
Name of School Corporation: MERRILLVILLE COMM. SCHOOL CORP **Corp ID:** 454600
Address of School Corporation: 6601 Delaware St
City: Merrillville **Zip:** 46410 **County Number:** 45
VIN: 4DRBUC8N6FB620486 **License Number:** 8023 **Bus Number:** 68
Make of Body: IC Corporation **Year:** 2015 **Make of Chassis:** IC Corporation **Year:** 2015
Bus Type: C **Mileage:** 29187
Inspection Status: R **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.