

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	12/22/2016	Time:	10:00 AM
Name of School Corporation:	ST JOHN LUTHERAN SCHOOL (57)	Corp ID:	220024		
Address of School Corporation:	301 S Oak Street				
City:	Kendallville	Zip:	46755	County Number:	57
VIN:	1GBHG31V541195656	License Number:	B826A	Bus Number:	1
Make of Body:	Collins Bus Corporation	Year:	2004	Make of Chassis:	Chevrolet
Bus Type:	A1	Mileage:	47120		
Inspection Status:	R	Inspected By:	Wes Rowlander	PE:	7427

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-1	The seat belt cutter is not located within the driver's reach
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.