## REPORT OF SCHOOL BUS INSPECTION

10:01 Type of Re-Inspection Date: 12/22/2016 Time: Inspection: AM Name of School Corporation: ST JOHN LUTHERAN SCHOOL (57) 220024 Corp ID: **Address of School Corporation:** 301 S Oak Street County City: Kendallville Zip: 46755 57 Number: License VIN: 1GBHG31V541195656 B826A **Bus Number:** Number: Make of Collins Bus Year: 2004 Chevrolet Year: 2004 Make of Body: Corporation Chassis: **Bus Type:** A1 Mileage: 47120 Inspected

By:

Wes Rowlader

PE:

7427

## Violations - Rejected

**Inspection Status:** R

**Inspection Description** Code

If bus manufactured after 5-2-1994, positive door opening device is missing or fails to 20-1-8

operate properly

**Violations - Out of Service** 

<u>Inspection Code Description</u>

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.