## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Post-Crash Inspection		Date:	1/4/2017	Time:	11:58 AM
Name of Schoo Address of Sch	I Corporation: E ool Corporation:	BROWNSBURG ( 310 Stadiun		L CORP.	Corp ID:	323305
City:	Brownsburg	Zip:	46112		County Number:	32
VIN:	1T7YT4A2761165163		License Number:	74956	Bus Number:	75
Make of Body:	Thomas Built Buses, א Inc.	<b>Year:</b> 2006	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2005
Bus Type:	D		Mileage:	124031		
Inspection Status:	0	Inspected By:	Edwin Davis		PE:	3981

## **Violations - Rejected**

Inspection Code	Description
103-1-1	See Notes: Any defect inspector deems a violation not listed

## Violations - Out of Service

Inspection Code	Description
59-2-2	Stop arm lights do not flash
59-2-1	Any stop arm light is inoperative
59-2-3	Stop arm does not fully extend to a right angle to the bus
65-2-1	Warning lights fail to operate correctly

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.