

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/24/2017	Time:	11:25 AM
Name of School Corporation:	SHENANDOAH SCHOOL CORPORATION	Corp ID:	333435		
Address of School Corporation:	5100 N Raider Rd				
City:	Middletown	Zip:	47356	County Number:	33
VIN:	4UZABRDU8ACAN3186	License Number:	74951	Bus Number:	41
Make of Body:	Thomas Built Buses, Inc.	Year:	2009	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	36308	Year:	2009
Inspection Status:	O	Inspected By:	Jeremy Mason	PE:	8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
25-2-2	Reflective glass is cracked, broken, or missing
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.