REPORT OF SCHOOL BUS INSPECTION

Type of 11:09 Time: Post-Crash Inspection Date: 2/3/2017 Inspection: AM Name of School Corporation: SHOALS COMM. SCHOOL CORP. 515520 Corp ID: **Address of School Corporation:** 11741 Ironton Rd County City: **Shoals** Zip: 47581 51 Number: License VIN: 4UZABRDC48CZ10604 B952D Bus Number: 11 Number: Thomas Built Buses, Year: 2008 Thomas Built Buses, Year: Make of Make of Body: 2008 Inc. Chassis: Inc. **Bus Type:** С Mileage: 64500 Inspection Inspected 0 PE: Mike Adams 7407 Status: By:

Violations - Rejected

Inspection Code	<u>Description</u>
61-1-5	See Notes: Any defect inspector deems a violation not listed
53-1-1	One (1) leaf spring is broken under the first two (2) leaves
53-1-4	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	<u>Description</u>
53-2-3	Coil springs, torque rods or torsion bars are broken or missing
53-2-5	"U" bolts are loose, broken, or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.