

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |               |                         |                          |
|---------------------------------------|--------------------------------|------------------------|---------------|-------------------------|--------------------------|
| <b>Type of Inspection:</b>            | Annual                         | <b>Date:</b>           | 2/10/2017     | <b>Time:</b>            | 9:07 AM                  |
| <b>Name of School Corporation:</b>    | BARTHOLOMEW CONS. SCHOOL CORP. |                        |               | <b>Corp ID:</b>         | 30365                    |
| <b>Address of School Corporation:</b> | 1260 N Marr Rd                 |                        |               |                         |                          |
| <b>City:</b>                          | Columbus                       | <b>Zip:</b>            | 47201         | <b>County Number:</b>   | 3                        |
| <b>VIN:</b>                           | 1GB3G3BGXD1146088              | <b>License Number:</b> | 26237         | <b>Bus Number:</b>      | W10                      |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.       | <b>Year:</b>           | 2013          | <b>Make of Chassis:</b> | Thomas Built Buses, Inc. |
| <b>Bus Type:</b>                      |                                | <b>Mileage:</b>        | 36771         | <b>Year:</b>            | 2015                     |
| <b>Inspection Status:</b>             | R                              | <b>Inspected By:</b>   | Travis Coryea | <b>PE:</b>              | 5892                     |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 69-1-3                 | Wiper blades are torn, cracked, brittle or otherwise deteriorated |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description