

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/1/2017	Time:	1:27 PM		
Name of School Corporation:	LEBANON COMMUNITY SCHOOL CORP.			Corp ID:	60665		
Address of School Corporation:	505 Ransdell Rd						
City:	Lebanon	Zip:	46052	County Number:	6		
VIN:	4DRBUAAN79B681591		License Number:	32492	Bus Number:	15	
Make of Body:	IC Corporation	Year:	2099	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	C			Mileage:	103904		
Inspection Status:	O	Inspected By:	Edwin Davis	PE:	3981		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
65-1-6	LED Lights have 25% to 49% of pixels inoperable.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.