

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/1/2017	Time:	2:17 PM
Name of School Corporation:	NORTH WEST HENDRICKS SCHOOLS			Corp ID:	323295
Address of School Corporation:	PO Box 70				
City:	Lizton	Zip:	46149	County Number:	32
VIN:	4DRBUAAP1EB352073			License Number:	B280L
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	35016	Year:	2014
Inspection Status:	O	Inspected By:	Edwin Davis	PE:	3981

## Violations - Rejected

### Inspection Code Description

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed
3-2-3	Battery compartment door will not open. Key must be available if battery door is locked
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.