REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	3/15/2017	**Time:** 9:35 AM
Name of School Corporation:	SWITZERLAND COUNTY SCHOOL CORP				**Corp ID:** 787775
Address of School Corporation:	1040 W Main St				
City:	Vevay	**Zip:**	47043		**County Number:** 78
VIN:	1HVBBAAPB3H579050		**License Number:**	B115L	**Bus Number:** 32
Make of Body:	IC Corporation	**Year:** 2003	**Make of Chassis:**	Blue Bird Corporation	**Year:** 2004
Bus Type:	C		**Mileage:**	144708	
Inspection Status:	O	**Inspected By:**	Chris Clark		**PE:** 6665

Violations - Rejected

Inspection Code	Description
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
40-1-1	Any required instrument or gauge is missing. (Speedometer, Odometer, Fuel Gauge, High beam, Brake indicator light or gauge, air pressure gauge, brake warning light, DEF Gauge)

Violations - Out of Service

Inspection Code	Description
14-2-2	Any crossmember is rusted sufficiently to weaken floor supports

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.