

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|-------------|-------------------------|-----------|
| Type of Inspection: | Post-Crash Inspection | Date: | 3/16/2017 | Time: | 10:31 AM |
| Name of School Corporation: | EASTERN PULASKI COMM SCH CORP. | Corp ID: | 666620 | | |
| Address of School Corporation: | 711 School Dr | | | | |
| City: | Winamac | Zip: | 46996 | County Number: | 66 |
| VIN: | 1GB0G2BG0B1152797 | License Number: | 18141 | Bus Number: | 26 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2011 | Make of Chassis: | Chevrolet |
| Year: | 2011 | Year: | 2011 | Year: | 2011 |
| Bus Type: | A1 | Mileage: | 49846 | | |
| Inspection Status: | R | Inspected By: | Tim Grayson | PE: | 7558 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 24-1-2 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.