

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/16/2017	Time:	10:31 AM
Name of School Corporation:	EASTERN PULASKI COMM SCH CORP.	Corp ID:	666620		
Address of School Corporation:	711 School Dr				
City:	Winamac	Zip:	46996	County Number:	66
VIN:	1GB0G2BG0B1152797	License Number:	18141	Bus Number:	26
Make of Body:	Thomas Built Buses, Inc.	Year:	2011	Make of Chassis:	Chevrolet
Bus Type:	A1	Mileage:	49846	Year:	2011
Inspection Status:	R	Inspected By:	Tim Grayson	PE:	7558

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.